

When Surface Finish Matters...

Industry: Chemical, product transfer Material: 304 Stainless Steel Case: 1502

Problem: This customer had ongoing problems with product adhesion and buildup on the surfaces of transfer lines and equipment. Rotary valves quickly became caked with product, not allowing a full "dump" of the product. The product buildup had slowed product transfer rates and lowered the system efficiency. The product production line was regularly shutdown to clean and remove caked material from the rotor veins.



Questions: Call or E-mail our Support Team 1-800-245-5707 info@harrisonep.com



Solution: The required surfaces were polished to Harrison C-75 specifications. All internal surfaces of the rotor veins were polished to reduce product adhesion. The inlet and outlet of the rotor body were also polished. The customer saw a reduction of product buildup and a significant increase in product transfer rates.

The customer added the C-75 polishing to the rotor valve's preventative maintenance schedule. All valves are reconditioned as they are rotated out and back into service.

Harrison Electropolishing, L.P. specializes in electropolishing, precision mechanical polishing, passivation, oxygen cleaning, and chemical cleaning of high purity stainless steel processing equipment. With Harrison Electropolishing, you will receive service from some of the best and most experienced craftsmen in our industry.

13002 Brittmoore Park Drive Houston, Texas 77041 832-467-3100 832-467-3111 fax www.harrisonep.com